

Computer Control Electronic Universal Testing Machine

TMA-100 M



1.Brief Information

Model TMA-100M Computer control electronic universal testing machine is designed and manufactured according to ASTM, ISO,DIN etc standards. It is computer-controlled precision testing machine, suitable for wide range of material for tension compression, bending and shearing test. It has high stability as well as high precision, equipped with PC system& printer for graph, test result display, test control as set program, printing & data processing. Complete with modulus for metal, spring, textile, rubber, plastic and other material testing & creep test. It is widely used in many field used in many fields such as industry factories, mineral enterprise and high schools.

2.Standard :

- •ISO527-6892:Metallic Materials-Tensile Testing At Ambient Temperature
- •ISO 14125-Fiber Reinforced plastic composites -deformation of flexural properties
- •ASTM A 370:Standard Test Methods And Definitions For Mechanical Testing Of Steel Products Tension Test
- •ASTM 1060 And So on



3.Features:

3.1 Host Frame

•The mainframe is a double-space door structure. The driving principle is that the motor drives the ball screw pair to rotate after decelerating through the reducer system, thus driving the middle beam up and down to complete the test, the transmission is stable and the noise is low.

•Using four guiding optical screws, φ 40mm high precision ball screw. The high rigid frame is composed of thick beam and base, which can guarantee the frame with excellent longitudinal and transverse rigidity and good overall accuracy.

•Servo motor drive and reducer system without maintenance, can guarantee the accuracy and stability of the beam ,the speed ratio can reach 1: 100000.

•Under the guidance of the internal control precision of 5% of coaxially, the cross joint can be precisely aligned in axial test, and the linear motion of the beam can be guaranteed, so as to ensure that the influence of the lateral force on the specimen under load is minimal. Thus, better test performance can be obtained.

3.2 Controller

•Force , displacement , deformation measurement resolution up to 1 / 300000 of full scale

•AD sampling frequency can be as high as 300 Hz

•Can realize closed-loop control of parameters such as test force, specimen deformation and beam displacement .It can be used to realize the tests of constant speed- test force, constant speed- displacement, constant speed- strain, constant speed-load cycle, constant speed-deformation cycle and so on. Various control modes can be switched smoothly. And smooth transition. Advanced Neuron Adaptive PID Control algorithm.

Mode	TMA-100M
max. test force	100KN(10.000 kg)
Test force testing range	1%~100%
Testing machine accuracy grade	0.5
Accuracy of test force	Better than indication value ±0.5%
Crosshead displacement resolution	0.001mm
Large deformation resolution	1/200000
Control system	servo drive controller
Auto-stop function	1.maximum capacity overload protection
	2.leakage current protection
Adjust speed range	0.005-500mm/min
Tensile test space	700mm
Compression test space	1100mm
Compression Diameter	100*100mm
Effective test width	475mm
Host type	door structure

4.1. Technical specification:

TEST MACHINES AUSTRALIA

Host dimension	840mm x 600mm x 2050mm
Weight	600kg
Power Supply	240volts, Single phase, 50 hertz
Working environment	Room temperature 45 humidity 20%-80%

4.2 Standard delivery:

NO.		Brand Name	
1	Test host		1
2	AC servo motor		1
3	Speed governor		1
<mark>4</mark>	Load cell		1
<mark>5</mark>	Precision ball screw	Taiwan ABBA	2
6	Deceleration system		1
7	Computer control		1
	system		
8	Optical encoder		1
9	Computer	Lenovo	1
10	Printer	Hp color ink jet printer	1
11	PCI Card		1
12	Windows system		1
	software		
<mark>13</mark>	Tensile accessory	Round jaw(mm) Φ 4- Φ 9, Φ 9- Φ 14, Φ	In total 6 sets
	For Metal Material	<mark>14-⊕20</mark>	customer choose
		Flat jaw 0-7,7-14,14-20	by yourself
<mark>14</mark>	Compression	100*100mm	1
	accessory		
<mark>15</mark>	Bending Fixture		1
15	Technical information		1



5.Max Test Software Interface

			Universal	Testing Machine Co	mputer System	···[Metallic materials	-Tensile testing at	ambient tempera	ture(ISO-689)	2)]			- X
	Mode(<u>M</u>)	Data(<u>D</u>)	Settings(<u>S</u>)	Debug(<u>U</u>)	Tools()	Window(<u>W</u>)	Help(<u>H</u>)	Test	Analyse	Clear	Data -	Previous	₽ Next
Load & B Stop	Extension (200) while destroy	Tensile	Lo	ad(kN) 0.	DISP MOD	De Extensor	eter(mm)-Extensor	ndet of the second s	i Displacen	nent (4946444) Displa	cement(mm)		0.0
	8	. 350		Maximum		5.1	184			ſ.			
Curve F Curve	Pad (000000000) type:	Load-Extension				► +	• २ 🥖	x 6 🗹 🖸	Control Disp	Pad 202222	ensior Tens	ile Program	88888
2.000-	Lond (kN)							HH HI (₹	Speed	0.0100 0	m/min)		₩ >
1.800-								_		Displ	acement (mm	/min)	•
1.400-									0.01	0.02	0.05 🗖	0.1 🖻	0.2 🏴
1.200-									0.5		2 =	5 =	10 =
1.000-									20 '	- 50 -	100 -	200 #	500 -
0.800-													
0.600-									Target:	se Loop Cont None	rol		Apply
0. 400-									會				v 1
0.200-								6.5		STA	RT	TOP	A STURN
0-	0 0.01	100 0. 0200	0.0300 0	0. 0400 0. 0500	0.0600	0.0700	0.0800 0.0	1900 0.100	Auto (Spee	return afte ad: 500)	r testing		

5.1.Test Interface



www.testmachines.com.au



5.2.Test Standard

System	Load Sensor	Extensometer	Control Setti	.ngs Advance		
Option Test		Test Standards	Ren	Remote Controler		
Caption	000527 1030 105 00 107	ID		- Find		
🗹 (E)Standar	d Test Methods for	Ten (ASTM E8)				
🗹 (E)Tensile	e testing as ambier	nt te (ISO-6893	2)			
BSEN 408						
🗹 Standard I	est Methods for Te	stinLS (ASTM	1061)			
✓ Standard T	est Methods and De	fini (ASTM A37)	0-2009)			
Metallic m	aterials-Compressi	.on t				
 □ Metallic m	aterials-3-Points	Bend				
	aterials-4-Points	Bend				
 Metallic m	aterials shear tes	ting		All		
Metallic m	eterials-Sheet en	t str (TSO 1027	5)	110/825		
	storials bheet and	L start (TSO 1021)	3)	Clear		
I III	aterials-pheet and	1 Str (150 1011-	3)			

6.Max Test Software features

6.1 Language selection: English and other languages interface freely switch operation,
6.2 Basic functions: calculate and list data graphics: the basic parameters of a material testing machine: (1).yield point(2).0.2% off set.(3). Yield strength(4). Tensile strength(5). Elongation(6). Energy absorption(7). Maximum(8). Rupture values(9). Deformation amount (10). Averages. More than twenty parameters contrast to graphics.

6.3 Multiple curve display mode: Stress - strain, Force - displacement, Force - time, Strength –Time and other curve patterns.

6.4 Control mode: fixed displacement, fixed speed, constant strain rate, fixed load, fixed load rate, fixed strain rate, etc.

6.5 Dynamic display: During the test, the load, elongation, displacement and experimental curves selected as testing, real-time dynamic display on the main screen.

6.6 Automatic identification ,storage: test conditions, test results, regression

6.7 Graphical Analysis: After the test is completed, you can use the mouse to view data from the test curve, any point on the test curve can be enlarged analysis, and choose Print.

6.8 Report Output: Graphics and arguments are opened to customers and can be modified as required. It can output different report formats, convenient and easy to learn practical



9.Some Pictures for your reference



Grips For Metal Material



Round jaw(mm):Φ4-Φ9, Φ9-Φ14, Φ14-Φ20 Flatjaw:0-7,7-14,14-20



Wire connection with ground wire Panel

Power Switch

Hand

For further information please contact:



0418 369 505 sales@testmachines.com.au www.testmachines.com.au